

## Release Notes EN RTW TouchMonitor Firmware 8-05

Software version:            rtw-tm-fw-8-05.bin

Build Date:                 August 26<sup>th</sup>, 2021

---



**ATTENTION!** – Please check the firmware version of your unit!  
Depending on that version interim updates shall be executed!  
Mandatory order of updates: 1-0 --> 1-15 --> 2-17 --> 2-30 --> 2-38 --> 5-11 --> then higher  
versions. Please contact us: support@rtw.com

---



**NOTE** – Copy the file to an USB flash drive. The USB flash drive shall be correctly  
unmounted. Not until then remove it from your computer and insert it into your TouchMonitor.



**ATTENTION!** – Disconnecting WITHOUT unmounting may damage the copied file and  
thus may cause malfunctions after update!

---

## Release Notes Firmware 8-05

### Updates

---

#### General

- A security vulnerability on the network interface has been closed.
- A license file (LF) for activating purchased licenses can now be loaded into the TouchMonitor from the root directory of the USB storage medium in addition to the folder "/rtw/licence".

#### SW20004

- If the devices run with firmware 8-05 and a surround sound analyzer license is purchased only then, the activation of the multi-channel license "SW20001: Multichannel Mode" is additionally required.

## Release Notes Firmware 8-04

### Updates

---

#### Ravenna Devices

- The Merging ZMAN software has been updated. Therefore, please perform an update of the implemented Ravenna network interface (Interface Firmware).

**Please install the RTW ZMAN firmware 1.0.11. This firmware is based on the Merging firmware version 1.1.5 and includes additional modifications from RTW. This RTW ZMAN firmware 1.0.11 shall not be used with other third party products.**

The Interface Firmware can be found on  
<https://www.rtw.com/en/support/manuals-software/downloads/audio-monitors/touchmonitor-tm9.html>  
or <https://www.rtw.com/en/support/manuals-software/downloads/audio-monitors/touchmonitor-tm7.html>

#### SW20002

- The SSA display and the SPL Sum were not displayed for audio groups with SPL selected as Loudness standard. This is now solved.

#### SW20014

- Failures in LQL operation have been fixed and the functionality has been improved.

## Important Notice

---

<b>Trademark</b>	All products and company names contained herein are ™ and ® of their respective holders.
<b>Copyright</b>	RTW GmbH & Co.KG Am Wassermann 25   50829 Cologne   Germany
<b>Support</b>	Visit <a href="http://www.rtw.com">www.rtw.com</a> for support information